Isle of Man Ship Registry Port State Control Notice



July to August PSC Analysis

Ref: 03-2022 Issued: 2nd September 2022

1. Introduction

This notice serves to highlight shipowners of recent trends identified following Port State Control Inspections performed across all Manx flagged vessels for July and August.

The top risk areas identified for these months were:


- Fire Safety
- Safety of Navigation
- Structural Condition

The Ship Registry advises owners to place particular emphasis on these risk areas during their own inspections to minimise issues during Port State Control. Any concerns/issues following Port State Control should be highlighted to the Ship Registry as soon as possible.

Owners are reminded of the joint <u>Concentrated Inspection Campaign</u> on STCW between 1st September 2022 and 30th November 2022 being ran by Paris and Tokyo MoU. Please refer to the end of this notice for further information.

2. PSC Deficiencies - All PSC MoU Regions

The following chart shows deficiency areas requiring corrective action raised in all MoU Regions expressed as a percentage of total inspections performed (including inspections with no deficiencies) i.e. 22% of all inspections raised a deficiency relating to fire safety:





3. PSC Deficiencies by Ship Type - All PSC MoU Regions

The following table shows deficiency items raised by code (Paris MoU coding system) by ship type in all MoU regions.

Deficiency Heading	Bulk Carrier	Gas Carrier	Container Ship	Oil Tanker	Cable Ship	Passenger HSC	Offshore Construction Vessel
02 - Structural							
Condition	3	1	0	1	0	1	0
145 - MARPOL Annex							
V	1	0	0	0	0	0	0
011 - Certs & Docs -							
Ship Certificate	4	1	0	0	0	0	0
11 - Life Saving							
Appliances	3	0	0	0	0	0	1
10 - Safety of							
Navigation	4	1	1	0	0	0	0
15 - ISM Related							
deficiencies	3	0	0	0	0	0	0
012 - Certs & Docs -							
Crew Certificates	0	0	0	1	0	0	0
07 - Fire Safety	3	2	0	3	0	2	1
141 - MARPOL Annex							
I	0	0	0	0	1	0	0
18 - MLC 2006 -							
Health Prot., Med.							
Care, Welfare and							
Social Security							
Protection	1	0	0	0	0	0	0
18 - MLC 2006 -							
Conditions of							
employment	2	0	0	0	0	0	0
99 - Other	0	0	0	0	0	1	0
144 - MARPOL Annex							
IV	0	0	0	0	0	1	0
04 - Emergency							
Systems	0	2	0	0	0	0	0
013 - Certs & Docs -							
Document	1	0	0	0	0	0	0
TOTAL	25	7	1	5	1	5	2



4. PSC Deficiencies - All

The following table shows all deficiencies that were raised to the IOM Ship Registry as a result of Port State Control.

Deficiency Heading	Code	Deficiency Description	Deficiency Comment
011 - Certificates &	0000	Certificate for Bunker oil	Bunker liability certificate missing and
Documentation - Ship	1137	pollution damage	records not maintained
Certificate	1137	Continuous synopsis	CSR form missing and records not
	1123	record	maintained
	1123	record	According to the DNV database, the
			1
			Tonnage Certificate has been issued in
			09/03/2022, but is not available on
			board. Only a cover letter of that date
			and the certificate issued 31/03/2016 is
			available. Several old statutory
			certificates, several of which can still be
			regarded as valid, are offered together
			with the most recently issued
			certificates. Only the most recently
			issued valid certificates may be
			available for the administration. To
		_	avoid misuse, the replaced certificates
	1132	Tonnage certificate	must be withdrawn or invalidated.
			Ship's type as per SMC is 'bulk carrier';
			the vessel is not constructed as per
			Convention requirements: e.g. no
			freefall lifeboat installed; the vessel is
			not provided with the necessary
			information: e.g. ESP documentation.
			The DoC mentions "the SMS of the
			Company has been audited and that it
			complies with the requirements of the
		Safety management	ISM Code for the type(s) of ships listed
		certificate (SMC/ISM	below: Bulk Carrier (Other cargo ship is
	1107	Code)	deleted)".
	1199	Other (certificates)	Lack of familiarity
012 - Certificates &			
Documentation - Crew		Seafarer Employment	
Certificate	1220	Agreement SEA	SEA found invalid and to be re-issued.
013 - Certificates &	1223	rigi dement der	
Documentation -		Signs, indications, WT	Emergency lighting not properly
Document	1310	door indicators	identified
02 - Structural			Hull corrosion several points of
Condition	2112	Hull - corrosion	corrosion
			Deck corrosion several points of
	2117	Decks - corrosion	corrosion on deck
			Not as required. Missing caps on the
	2105	Steering gear	solenoid.
		Enhanced survey	ESP documentation is missing. The ship
	2119	programme (ESP)	type as per SMC is 'bulk carrier'.
		Closing devices/watertight	Weathertight doors not sealing
	2101	doors	correctly
	2101		Correctly
	2400	Electric equipment in	Landa of Carrellia II
	2108	general	Lack of familiarity



04 - Emergency		Emergency towing	
Systems	4107		
	4108	Muster list	Lack of familiarity
07 - Fire Safety	7102	Inert gas system	IGS inoperative
		Evaluation of crew	Fire drill training to be improved by all
	7125	performance (fire drills)	crew members
		Fixed fire extinguishing	Inoperative. Foam system not ready for
	7109	installation	use.
7101		Fire prevention and structural integrity	Deck head SFP sagging; possible leakage on fire line.
	7 2 0 2	Fire detection and alarm	Smoke detector head failed to activate
	7106	system	in Starboard engine room
	7199	Other (fire safety)	Lack of familiarity
	7105	Fire doors/openings in fire-resisting divisions	Lack of familiarity
		<u> </u>	Lack of familiarity
	7113	Fire pumps and its pipes Fire-dampers	Fire pumps and piping not as required Fire dampers not as required
	/113	Evaluation of crew	The dampers not as required
	7125	performance (fire drills)	Fire drill to be improved
	7105	Fire doors/openings in fire-resisting divisions	Fire doors of A60 type - held open by tie back hooks.
10 - Safety of			Magnetic compass light inoperative and
Navigation			compass not visible from steering
	10105	Magnetic compass	position
		Coord and distance	Speed log reading is 11.8kn, vessel
	10118	Speed and distance indicator	moored. Device is showing incorrect reading.
	10110	Indicator	SB Pilot ladder as found rigged and
			used is unsafe. Strength of the ropes
			used to connect the ladder to the
			strong points on deck is not confirmed.
			The available pilot ladder stored
		Dilat laddana and baiat /	amidship with excessive play between
		Pilot ladders and hoist / pilot transfer	choks and steps, steps are unstable. Railing in way of the PS pilot access
	10101	arrangements	point is damaged.
	10133	Bridge operation	Lack of familiarity
	10116	Nautical publications	IAMSAR old edition
		The state of the s	Overhead clearance missing in the
	10127	Voyage of passage plan	voyage plan
11 - Life Saving	1.		Lifejacket lights found inoperative and
Appliances	11118	Lifejackets	not attached to lifejackets
	11101	Lifohooto	The vessel is not provided with a free-
	11101	Lifeboats	fall lifeboat. Life saving appliances marking of
	11199	Other (life saving)	equipment not marked as required.
	11101	Lifeboats	Call sign missing on the free fall
141 - Pollution	1		J
Prevention - MARPOL			
Annex I	14104	Oil filtering equipment	OWS inoperative
144 - Pollution Prevention - MARPOL Annex IV	14402	Sewage treatment plant	Test records of free-Chlorine not found as required
			•



145 - Pollution Prevention - MARPOL Annex V	14501	Garbage	Excessive garbage on board to be disposed ashore
15 - ISM - Related deficiencies	15150	ISM	ISM internal audit to be conducted within 3 months
	15107	Emergency preparedness	ISM: Emergency preparedness to be improved.
	15150	ISM	Corrective action on ISM within 3 months.
18 - MLC 2006 - Conditions of employment	18299	Other - (Conditions of employment)	In ER several floorplates purifier area, A/E area not secured. Floorplates with handle for lifting not secured by hinges.
	18299	Other - (Conditions of employment)	Lack of transparency regarding shore leave.
18 - MLC 2006 - Health Protection, Medical Care, Welfare and Social Security Protection	18417	Anchoring devices	Anchor chain bitter end release arrangements are deformed, removal of the PS pin could not be demonstrated, SB side not verified.
99 - Other	99102	Other (SOLAS operational)	SAR plan to provide to PA



5. Joint Concentrated Inspection Campaign

From 1st September 2022 – 30th November 2022, the Paris and Tokyo MoU regions are running a joint concentrated inspection campaign on STCW. The CIC inspections will apply to all ships and will be conducted in conjunction with regular Port State Control inspections.

A ship will be subject to only one CIC inspection during the period of the campaign. During the inspection PSC officers will use a list of pre-defined questions. Where deficiencies are found, it is treated the same as a deficiency found during PSC and actions taken can vary from recording the deficiency up to detention of the vessel depending on the deficiency and its severity. The CIC questionnaire is shown below:

2022 CONCENTRATED INSPECTION CAMPAIGN ON STCW 01/09/2022 - 30/11/2022					
Inspection Authority					
Ship Name		IMO Number			
Date of Inspection		Inspection Port			

QUESTIONS 1 TO 10 ANSWERED WITH A "NO" MUST BE ACCOMPANIED BY A RELEVANT DEFICIENCY ON THE REPORT OF INSPECTION

No.	Item	Yes	No	N/A	Detention
Q.1*	Do the number of the seafarers serving on board conform with the Minimum Safe Manning requirement specified for the vessel?				
Q.2*	Do the master and officers hold valid certificates of competency as required by the Minimum Safe Manning Document?				
Q.3*	Do the master, officers and radio operators hold valid endorsements attesting the recognition of certificates or documentary proof of application?				
Q.4*	Do seafarers hold relevant certificates of proficiency (COP) or documentary evidences?				
Q.5*	Do seafarers on board hold valid medical certificates?				
Q.6	Do the records for hours of rest indicate compliance with the requirements?				
Q.7	Do the watch schedules comply with the provisions of STCW?				
Q.8*	Are seafarers newly joined the vessel familiar with their specific duties that are relevant to their routine or emergency duties?				
Q.9*	Can the seafarers on board the vessel communicate effectively with each other in the working language of the vessel?				
Q.10	Do the voyage plans cover the whole route from berth to berth?				

Note: If "No" is ticked for questions with an asterisk " \ast ", the ship may be considered for detention

