

Isle of Man Ship Registry Port State Control Notice

November 2024 PSC Analysis

Ref: 10-2024

Issued: 17th December 2024

1. Introduction

This notice serves to highlight shipowners of recent trends identified following Port State Control Inspections performed across all Manx flagged vessels for November 2024.


The top risk areas identified were:

- Fire Safety
- Water / Weathertight Condition
- Emergency Systems
- Safety of Navigation

The Ship Registry advises owners to place particular emphasis on these risk areas during their own inspections to minimise issues during Port State Control. Any concerns/issues following Port State Control should be highlighted to the Ship Registry as soon as possible.

2. PSC Deficiencies – All PSC MoU Regions

The following chart shows deficiency areas requiring corrective action raised in all MoU Regions as a percentage of total deficiencies recorded:



3. PSC Deficiencies by Ship Type – All PSC MoU Regions

The following table shows deficiency items raised by code (Paris MoU coding system) by ship type in all MoU regions.

Deficiency Heading	Anchor Handler / Supply	Bulk Carrier	Cargo Ship	Oil/Chemical Tanker	Total
013 - Certificates & Documentation - Document		1			1
03 - Water / Weathertight Condition		2			2
04 - Emergency Systems		2			2
07 - Fire Safety				3	3
10 - Safety of Navigation		1	1		2
11 - Life Saving Appliances	1				1
141 - Pollution Prevention - MARPOL Annex I				1	1
18 - MLC 2006 - Conditions of employment				1	1
18 - MLC 2006 - Health Protection, Medical Care, Welfare and Social Security Protection				1	1
Total	1	6	1	6	14

4. PSC Deficiencies – All

The following table shows all deficiencies raised to the IOM Ship Registry due to Port State Control for the months of November 2024

Deficiency Heading	Code	Description	Comment
013 - Certificates & Documentation - Document	01308	Records of rest - Records of seafarer's daily hours of work or rest	
03 - Water / Weathertight Condition	03104	Cargo and other hatchways	Several cargo hold hatch covers not able to close weathertight
	03104	Cargo and other hatchways	Hatch cover rubber seals missing at several hatch covers on deck
04 - Emergency Systems	04103	Emergency lighting, batteries and switches	One light in the Emergency Generator room out of order
	04113	Water level indicator	Water ingress alarm panel - main alarm and sensor fail alarm active for FPT, Bosun store and forward void space
07 - Fire Safety	07105	Fire doors/openings in fire-resisting divisions	Not as required
	07106	Fire detection and alarm system	Not as required
	07111	Personal equipment	Not as required
10 - Safety of Navigation	10104	Gyro compass	Gyro failure alarm active at wheelhouse control panel
	10129	Navigation records	
11 - Life Saving Appliances	11108	Inflatable liferafts	Each survival craft shall be stowed so that neither the survival craft nor its stowage arrangement will interfere with the operation of any other survival craft or rescue boat at any other launching station. PSCO observed improper stowage arrangement of port and starboard inflatable liferafts which could prevent the float-free capabilities. Life rafts were installed with two rafts stowed above three liferafts with securing straps that in the event the top HRU's failed, it would



			prevent the life rafts from floating free.
141 - Pollution Prevention - MARPOL Annex I	14119	Oil and oily mixtures from machinery spaces	Oil leaks
18 - MLC 2006 - Conditions of employment	18201	Fitness for duty - work and rest hours	Missing hours of rest in September
18 - MLC 2006 - Health Protection, Medical Care, Welfare and Social Security Protection	18401	Medical equipment, medical chest and medical guide	Missing equipment

