Isle of Man Ship Registry Port State Control Notice



May 2024 PSC Analysis

Ref: 05-2024 Issued: 13 June 2024

1. Introduction

This notice serves to highlight shipowners of recent trends identified following Port State Control Inspections performed across all Manx flagged vessels for May 2024.


The top risk areas identified during this month were:

- MLC 2006 Accommodation, Recreational Facilities, Food & Catering
- MLC 2006 Health Protection, Medical Care, Welfare & Social Security Protection
- Fire Safety

The Ship Registry advises owners to place particular emphasis on these risk areas during their own inspections to minimise issues during Port State Control. Any concerns/issues following Port State Control should be highlighted to the Ship Registry as soon as possible.

2. PSC Deficiencies - All PSC MoU Regions

The following chart shows deficiency areas requiring corrective action raised in all MoU Regions as a percentage of total deficiencies recorded:





3. PSC Deficiencies by Ship Type - All PSC MoU Regions

The following table shows deficiency items raised by code (Paris MoU coding system) by ship type in all MoU regions.

Vessel Subtype	Bulk	Cargo	Gas	Total
	Carrier	Ship	Carrier	
011 - Certificates & Documentation - Ship Certificate		1		1
03 - Water / Weathertight Condition		1		1
04 - Emergency Systems			1	1
07 - Fire Safety	1	1		2
092 - Working & Living Conditions - Working Conditions		1		1
10 - Safety of Navigation			1	1
11 - Life Saving Appliances		1		1
13 - Propulsion & Auxiliary Machinery		2		2
144 - Pollution Prevention - MARPOL Annex IV		1		1
146 - Pollution Prevention - MARPOL Annex VI	1			1
15 - ISM - Related deficiencies		1		1
18 - MLC 2006 - Accommodation, Recreational Facilities, Food				
& Catering		3		3
18 - MLC 2006 - Health Protection, Medical Care, Welfare and				
Social Security Protection		2	1	3
Total	2	14	3	19

4. PSC Deficiencies - All

The following table shows all deficiencies raised to the IOM Ship Registry due to Port State Control during May 2024.

Deficiency Heading	Code	Description	Comment
011 - Certificates & Documentation - Ship Certificate	01199	Other (certificates)	Various certificates
03 - Water / Weathertight Condition	03112	Scuppers, inlets and discharges	Scuppers plug
04 - Emergency Systems	04121	Crew familiarisation with Emergency Systems	Crew familiarization
07 - Fire Safety	07106	Fire detection and alarm system	One fire detector in steering gear room detached
	07199	Other (fire safety)	Main engine control room panel board back stored a combustible material (carton)
092 - Working & Living Conditions - Working Conditions	09298	Other (accident prevention)	Spare parts not secured
10 - Safety of Navigation	10116	Nautical publications	Nautical publications
11 - Life Saving Appliances	11104	Rescue boats	Not properly maintained. Several reflector stripes blind and dirty.
13 - Propulsion & Auxiliary Machinery	13108	Operation of machinery	Fire door handle stuck
	13199	Other (machinery)	Number 2 main air compressor oil leaking



144 - Pollution Prevention - MARPOL Annex IV	14402	Sewage treatment plant	Sewage plant small leakage
146 - Pollution Prevention - MARPOL Annex VI	14610	Operational procedures for engines or equipment	Lack of familiarity. Engine crew unfamiliar with incinerator alarm resets
15 - ISM - Related deficiencies	15101	Safety and environmental policy	Garbage not separated
18 - MLC 2006 - Accommodation, Recreational	18304	Lighting - (Accommodation)	Workshop lights
Facilities, Food & Catering	18313	Cleanliness	Not as required. Room at Bosun Store fwd starboard side full of old lashing equipment and old ropes.
	18313	Cleanliness	Oily box
18 - MLC 2006 - Health	18416	Ropes and Wires	Rope line
Protection, Medical Care, Welfare and Social Security Protection	18424	Steam pipes, pressure pipes, wires (insulation)	Auxiliary boiler
	18425	Access / Structural features of ship	Various equipment

